



1/4 Cor. Secs. 32 & 33.  
Fd 1" Iron Pipe with brass cap.  
2 B.T.'s  
Mag. Var. 21°00' E.

Set 3/4" Iron Pipe

N 89° 55' E  
1318.6

5274.3  
660

Set 1/2" Iron Pipe

1977.2

1/4 Cor. Secs. 33-34. Fd 1"  
I.P. with brass cap - 2 O.B.T.'s  
both in bad shape. Bl. E. Scr. N.B.T.  
20" F.I., N 41° 39' W, 498 ft. Marked.  
1/4 S-33, R.B. 2741, B.T.  
Mag. Var. = 21°00' E.

South 1320.0

Lookingglass Creek  
Corner is in Creek  
Set 1/2" Iron Pipe on  
South bank for Wit. Cor.  
Pipe bears South 20° ft  
from cor.

All bearings in this survey were determined by the method of deflection angles referred to a meridian established by a solar observation taken during this survey.

**SURVEY TO ESTABLISH PROPERTY LINES  
IN THE S 1/2, SEC. 33, T27S, R7W, W.M.  
DOUGLAS COUNTY, OREGON**

GRANT AND EVANS, ENGINEERS  
ROSEBURG, OREGON  
SURVEYED, MAY 1952, BY  
A. R. EVANS, REG. PROF. ENGINEER  
SCALE 1" = 400'



**COUNTY SURVEYORS WILL  
DO NOT REMOVE FROM OFFICE**

C.S. File # 11/88

Map File M/6+28

D.S. 41/88  
M 16-28

47/88