



SURVEY TO RE-ESTABLISH
OBLITERATED 1/4 CORNER OF
SECTIONS 4-5, T299R5W.WM.
DOUGLAS COUNTY, OREGON

GRANT & EVANS, ENGINEERS
ROSEBURG, OREGON
SURVEYED AUG. 11-13, 1953
SCALE 1" = 500'



T289 RSW
32 33
5 4
FD CEDAR POST IN FENCE LINE
AND 3 B.T.S. W.O. N78°E, 148.8
B.O. S66°W, 170.7 FT.
B.O. N28 1/2°W, 68.8 FT.

T299 RSW
SOUTH 5326.2 (RECORDED)
N60°21'W, 2182.2 = NORTH 2686.2 (REC)

1/4 COR SECS. 4 & 5, SET BY PROPORTIONATE
MEAS. SET 1 1/4" I.P. 2 B.T.S.
24" W.O. S69 1/2°W, 57.7 FT.
12" W.O. S33 3/4°W, 67.9 FT.
FD CORNER SET ERRONEOUSLY. S61°06'W,
12.0 FT FROM ACTUAL CORNER POSITION.
I.P. KNOCKED OUT BY TRACTOR. POSITION,
DETERMINED FROM B.T.S. W.O. S70°W, 45',
S28°W, 57.5 FT.

S 6°21' E, 5516.6
N60°21'W, 2134.4 = NORTH 2640.0 (REC)

FD. 1" I.P. 4 B.T.S.
24" LAUREL, WEST 60.0 (O.B.T.)
24" LAUREL N 35°W, 107.0 FT.
24" FIR N 78°E, 80.0 FT.
10" MAPLE, S71°E, 113.0 FT.

COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE