

N. 87° 42' E.

1266.9

1299.9

Set 5/8" rebar at
Fence corner

FILED
RECEIVED

DEC 20 1977

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Set 5/8" rod on
fence
Found 1" iron
pipe
Found 3/4" iron pipe

1318.8

N. 3° 38' W. 403.0
N. 89° 38' W. 24.3

411.0 ft. No. 24

224

1370.9
975.8

REGISTERED
OREGON
LAND SURVEYOR
Wilford N. Haines
MAY 7, 1948
WILFORD N. HAINES
239

Set 5/8" rebar
8.0 ft S. 3° 38' E. of
point in creek

Set 5/8" rebar
Rob. point
N. 61° 24' E. 97.8
N. 79° 59' E. 242.0

Found 1" iron pipe

28" fir S. 37° W. 64.5 ft.
with two blades
Looks like B.T.

Monument
shows
on M2-37
may have been
destroyed by
Road construction
7/64

SURVEY FOR DEED DESCRIPTION
SECTION 6, T23S., R5W. W.M

For
Woolley Enterprise inc. Drain, Oregon.

Oct 17, 1977

SCALE 1" = 100'

COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE

1/2 Cor. Sects. 547
Found 1" iron pipe
2 B.T.

North
Bearings based on
N. 0° 22' E. 838.8
M2-39

1/4 Corner Sects. 6+7
T. 23S., R. 5W. W.M.
Found County
Brass cap

MAP FILE M. 68-2

MAP FILE M. 68-2

ROAD

County