

Resurvey of Section 6, T32S, R7W and Resurvey & Subdivision of Section 1, T32S, R8W, W.M.

Roseburg Lumber Company

Scale: 1" = 500'

April 4, 1980

FILED
RECEIVED
APR 30 1980
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

Legend

- Monument Found
- Monument Set
- Section or Property Line
- Line marked with BLM tags



Bearings based on Cadastral resurvey of the South line of Sec. 6.

I ran a closed traverse around the exterior of Sec. 6 & Sec. 1 and through the interior of Sec. 1. I used a Jena 1 second theodolite and a Mac I-E EDM. I achieved a precision of 1:17,370 on the exterior and 1:18,433 on the interior and adjusted both traverses by the Crandall method. I set the corners between Sec. 6 & Sec. 5 by proportion based on the original survey distance and the interior corners in Sec. 1 by standard subdivision procedure based on the location of existing corner monuments.

Howard W. Johnstone P.O. Box 1088 Roseburg, Oregon

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Howard W. Johnstone

OREGON
MAY 13, 1960
HOWARD W. JOHNSTONE
498

