

FILED &
RECEIVED &
MAY 22 1980
COUNTY SURVEYOR
DEGLAS COUNTY, ORE
&

Found 3/4" iron pipe
North 1/4 Sect 4
T.22S., R.5W. W.M.

1318.60
1017.45
South
318.33

West 400.00

Set 5/8" x 40" Rebar
drove steel
fence post
along side

Set 5/8" x 40" Rebar
drove steel
fence post
along side

1002.82

W 1/2 NE 1/4 Sect. 4, T.22S., R.5W. W.M.
for
Earl HARRIS
Scale 1" = 100'
DRAIN OREGON
MAY 5, 1980

Parking

Truck Shop

10.5 ACRES

Wilford N. Haines
Rt. 38 Box 2
Drain, Oregon.

North
Bearing this survey are
based on assumption
that N 1/2 of Sect 4 is
North.

Drove steel
fence post
on line

(130)
Found
R/W
Bot. point
only R/W

Set 5/8" x 40" Rebar
on top of
Red Bank

(170)
SH R/W Found
5/8" rebar
90° with
cap

Found
1" iron
pipe
N.C. 1/2
Sect. 4

County R. 37
SMITH RIVER ROAD
107+93.4
(150)
SH R/W Found
5/8" rebar with
cap
R.W.

(100)
SH R/W Found
5/8" rebar
with
cap
N. 65° 00' E.
123.80

(100)
SH R/W Found
5/8" rebar
with
cap
N. 35° 52' E. 259.69

ROAD
N. 62° 24' E.
152.05

43.21

STATE
R.W. 112+50

38

114+50

110+00

This survey started at N 1/4 Sect. 4, Ran
South along center line to the State High-
way, thence along access road back to the
point of beginning, tying to monuments
shown found.
From this Travers I calculated position to
set corners

REGISTERED
OREGON
LAND SURVEYOR

Wilford N. Haines

MAY 7, 1948
WILFORD N. HAINES
239

LAND SURVEYORS FILE BOOK
DO NOT REMOVE FROM OFFICE