MAP FILE M86 - 70

COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE

FILED ✓
RECEIVED ✓

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

✓

Applegate st.

Found 1" iron pipe 1 ft.± under ground drove 5/8"x40' Rebar in center of pipe

Lot 3 BLOCK 32 South Drain
N.E. 1/4 of the SW 1/4 Sect 17, T.22S., R.5W., W.M.
Scale 1"=50' Feb. 10, 1981

REGISTERED
OREGON
LAND SURVEYOR
Wilford N. Haines
MAY 7, 1948
WILFORD N. HAINES
239

Record 750.00

STREET

The purpose of this Survey is to mark boundrys and Corners of the East one half of Lot 3 Block 32 South Drain.

This Survey started at the Northeast corner of Block 22 South Drain. Ran south along cedar st. an tied to a p.k. Nail at intersection of lane + cedar streets. From this information I proportion the lot corners on cedar street. As there is no known point to the west The East and West lines were made west record distance

For
David Cooper
Drain, oregon 97435
phone 836-2536

By
Wilford N Haines
Rt. 38 Box 2
Drain, ore. 97435
phone 836-2303

~~Drain~~ · ~~AVE.~~ · · 40

Standard oil Bulk plant 1

757.52

N.0° 36' E.

2 used road

40.47

32

West 80.00

N 0° 36' E 80.94

80.94

West 80.00

6

3

5

4

80.94

drove R.R. spike in pavement

curb

30.0

30.0

Found PK Nail M 62-37

CEDAR

EAST 400.87

Brass cap bench mark

Fd. bolt N.0°06'30" E. 40.55 ft.

Fd. bolt M 21-59

Set 5/8" x 40" Rebar 5

North Based on M 21-59

~~LANE~~ · SF.

MAP FILE M86 - 70