

Found 1/2" iron pipe  
M 14-50

N 89° 06' W  
M 14-50  
Basis of Bearings  
used

NW Corner  
D.L.C. # 37

Found

48" Fir 838° E 100.1165  
Now Very rotten stub  
with pitchy slab of old face  
No trace of old 12" fir  
5.58° E.

Set 5/8" x 48" Rebar with  
1/8" Brass disk inscribed  
Wilford N. Haines  
Drain, Ore. # 239

Blazed + Scribed  
14" Doug. Fir  
S 42° 20' E 66.9 ft.

N 88° 23' W.

1958.4

2646.72

N. 89° 06' W.

old California Road  
1107.10 West  
16.77 chs.  
Record 16.30 chs.

1205.8

N.E. Cor. DLC  
# 37

Fd. Corner  
Tree

Found  
2" iron pipe  
No trace of  
old fence corner  
M 14-50

2528.33

North  
Basis of Bearings  
M 14-50

T. 21 S., R. 5 W., W. M.

Sect. 25, SW 1/4 SW 1/4  
Sect. 26, SE 1/4 SE 1/4 + SW 1/4 SE 1/4  
Sect. 35, NW 1/4 NE 1/4

DLC # 37

Scale 1" = 200'

May 1982

FILED  
RECEIVED

JUL 7 1982

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

© Monument found

• set 5/8" x 40" rebar with 1/8" disk inscribed  
Wilford N. Haines, Drain, Ore.  
# 239

For

E.O. Breier  
Rt. 1 Box 325  
836-2657  
Drain, Ore. 97435

Leroy Churchill  
Rock Creek Rd  
836-2646  
Drain, Ore. 97435

Set 5/8" x 40" rebar  
with 1/8" Brass disk  
inscribed

Wilford N. Haines  
# 239

Blazed + Scribed  
30" D. Fir  
S 35° W 3.9 ft.

Vol 710 Page 790  
10.26 chs = 677.16 ft.

677.16  
S. 1034' W.

Fd. T. iron  
Int. Corner DLC # 37

Wilford N. Haines  
Rt. 38, Box 2  
Drain, Ore. 97435  
803-836-2303



COUNTY SURVEYORS FILE DATA  
DO NOT REMOVE FROM OFFICE

MAP FILE M. 92 - 30

MAP FILE M. 92 - 30