



- LEGEND
- Corner Found, 5/8" Iron Rod, or as described. ●
 - Corner Set, 5/8" x 3/4" Iron Rod with Alum. Cap marked "Shaner Engineering, LS 430", or as described. ○
 - Chain link fence. —+—+—+—+—

NARRATIVE

The boundary survey was done in July & August, 1987, using a Jena 01" Theodolite and a Mac II Electronic Distance Meter. The survey was based upon the Deed and adjacent Subdivision surveys. The Carnes Road R/W was determined by Deed records' distances and a tie to the Hillside Gardens subd. survey.



PROPERTY BOUNDARY SURVEY
OF
GREEN SCHOOL
IN THE NW 1/4 of Sec. 11, T28S, R6W, W. M.
For: Douglas County School District No. 4
1419 Valley View Drive
Roseburg, Oregon 97470
By: Shaner Engineering, Inc.
P.O. Box 1430
Roseburg, Oregon 97470

August 17, 1987