

# ESLICK CADASTRAL CONTRACT #53-04T0-0-2030S

FILED  
 FEB 22 1991  
 COUNTY SURVEYOR  
 DOUGLAS COUNTY, ORE.  
 P

MAP FILE M111-472-D

CORNER NO.	MONUMENT	ACCESSORIES	CORNER NO.	MONUMENT	ACCESSORIES
1	Found 3" Aluminum Cap on a 2 1/2" Aluminum Pipe per CS M91-55	Found B.T.: 48" Fir, healed face, Tag, bears N44°W, 29.00' per CS M91-55 28" Fir, healed face, Tag, bears N54°E, 44.0' per CS M91-55 20" Alder, B.S., Tag, bears S01°E, 34.5' per CS M91-55 34" Fir, healed face, Tag, bears S70°W, 59.8' per CS M91-55	11	Set 3" Aluminum Cap on 2 1/2" X 30" Aluminum Pipe	Mkd. B.T.: 45" Western Red Cedar, F.S. "CE1/16 S35 BT", Tags & Washer, bears N67°30'W, 50.47' to SC 36" Western Red Cedar, F.S. "CE1/16 S35 BT", Tags & Washer, bears S3°E, 31.50' to SC
2	Found 3" Aluminum Cap in rock, per M91-54B	Found B.T.: 68" Douglas Fir, healed face & Tag, bears N18°E, 57.4' to SC per CS M91-54B 16" Douglas Fir, healed face & Tag, bears S22°W, 21.9' to SC per CS M91-54B	12	Set 3" Aluminum Cap on 2 1/2" X 30" Aluminum Pipe	Mkd. B.T.: 53" Maple (1 of 5), F.S. "SE1/16 S35 BT", Tags & Washer, bears N86°15'W, 46.29' to SC 22" Douglas Fir, F.S. "SE1/16 S35 BT", Tags & Washer, bears N61°E, 101.17' to SC
3	Found 3" Aluminum Cap on 2 1/2" Aluminum Pipe, per M91-54B	Found B.T.: 23" Douglas Fir, healed face & Tag, bears N35°W, 19.8' to SC per M91-54B 22" Douglas Fir, healed face & Tag, bears N5°E, 33.3' to SC per M91-54B 23" Douglas Fir, healed face & Tag, bears S01°E, 21.4' to SC per M91-54B	13	Set 3" Aluminum Cap on 2 1/2" X 30" Aluminum Pipe	Mkd. B.T.: 38" Douglas Fir, F.S. "T20S R11W S25 BT", Tags & Washer, bears N25°15'E, 39.45' to SC 16" Douglas Fir, F.S. "T20S R11W S36 BT", Tags & Washer, bears S76°30'E, 13.77' to SC 40" Douglas Fir, School Marm, F.S. "T20S R11W S26 BT", Tags and Washer, bears N20°30'W, 3.12' to SC Set R.M.: Std. U.S.F.S. Disk "RM T20S R11W S26 S83°11'E, 40.56' 1990 RLS2244, bears N83°11'W, 40.56'
4	Set 3" Aluminum Cap on 3/4" X 38" finned Aluminum Rod	Mkd. B.T.: 20" Maple, F.S. "W1/16 S35 BT", Tags, bears S10°45'E, 39.01' to SC 17" Maple, F.S. "W1/16 S26 BT", Tags, bears N61°30'E, 21.81' to SC, at West end of fence. Found: Iron Fence Post bears N50°W, 0.60'	14	Set 3" Aluminum Cap on 2 1/2" X 30" Aluminum Pipe	Mkd. B.T.: 44" Douglas Fir, F.S. "N1/16 S36 BT", Tags & Washer, bears N73°15'E, 59.13' to SC 19" Maple, F.S. "N1/16 S36 BT", Tags & Washer, bears N86°E, 21.80' to SC 25" Douglas Fir, F.S. "N 1/16 S35 BT", Tags & Washer, bears N87°30'W, 32.15' to SC
5	Set 3" Aluminum Cap on 3/4" X 38" finned Aluminum Rod in Pasture	Mkd. B.T.: 18" Douglas Fir, F.S. "NW1/16 S35 BT", Tags, bears N78 1/4°W, 198.51' to SC Mkd. B.O.: End of Wing Wall of Northwest Corner of Bridge over Eslick Creek, bears S13°15'W, 827.21'	15	Set 3" Aluminum Cap on 2 1/2" X 30" Aluminum Pipe	Mkd. B.T.: 22" Douglas Fir, F.S. "E1/4 S35 BT", Tags & Washer, bears N20°30'W, 61.00' to SC 31" Douglas Fir, F.S. "W1/4 S36 BT", Tags & Washer, bears N3°E, 21.25' to SC 31" Douglas Fir, F.S. "W 1/4 S36 BT" Tags & Washer, bears S45°E, 6.10' to SC Mkd. B.O.: 5' high Rock Face, with P.K. Nail and Washer in the center of an "X" and Tag, bears N58°W, 18.60'
6	Found 2 1/2" Brass Cap on 1 1/2" O.D. Iron Pipe, 12" high; along side 2" O.D. Iron Pipe, 14" high, per CS 41-119 & CS 53-66	Found B.T.: 20" Maple, healed face, bears N69°E, 74.8' (76' per CS 41-119) to SC 12" Maple, healed face, bears S38°W, 93.2' (96' per CS 41-119) to SC Mkd. B.T.: 13" Alder, B.S. "T20S R11W S1/4 S26 BT", Tags & Washer, bears N07°30'W, 14.10' to SC Mkd. B.O.: Rock, 2.65' high, 4.5' long, 2.4' wide, with "X" and tag, bears N78°E, 3.79'	16	Set 3" Aluminum Cap on 2 1/2" X 30" Aluminum Pipe	Mkd. B.T.: 15" Douglas Fir, F.S. "S1/16 S35 BT", Tags & Washer, bears N30°W, 31.68' to SC Set R.M.: Std. U.S.F.S. Disk, mkd. "RM S1/16 S35 S88°04'E, 53.26' 1990 RLS2244", bears N88°04'W, 53.26'
7	Set 3" Aluminum Cap on 2 1/2" X 30" Aluminum Pipe	Mkd. B.T.: 28" Douglas Fir, F.S. "CN1/16 S35 BT", Tags & Washer, bears N64°E, 27.64' to S.C. 22" Douglas Fir, F.S. "CN1/16 S35 BT", Tags & Washer, bears S61°45'E, 22.34' to S.C.	17	Found 2" Brass Cap on 2" Iron Pipe, per CS M84-62	Found B.T.: 10" Douglas Fir, with "X" at B.H., bears West, 12.2' to SC 12" Douglas Fir, with visible Scribe, bears N44°W, 12.9' to SC 17" Douglas Fir, with healed face, bears S49°E, 7.5' to SC 11" Douglas Fir, with healed face, bears S24°W, 3.4' to SC
8	Set 3" Aluminum Cap on 2 1/2" X 30" Aluminum Pipe	Mkd. B.T.: 25" Douglas Fir, F.S. "C1/4 S35 BT", Tags & Washer, bears N22°45'E, 90.63' to SC Mkd. B.O.: P.K. Nail with Washer in Rock Face & Tag, bears N42°30'W, 112.96' Power Pole #10-121 with Tag, bears N68°W, 113.88' Set R.M.: Std. U.S.F.S. Disk mkd. "RM C1/4 S35 S0°12'W, 63.18' 1990 RLS 2244", bears N0°12'E, 63.18'	18	Found 2" Brass Cap on Iron Pipe	Found B.T.: Original 52" Cedar, healed face, bears S87°W, 15.8' to SC 12" Hemlock, healed face, bears N70°W, 21.5' to SC 33" Cedar, healed face, bears S61°E, (S61°W per CS53-66) 32.7' to SC
9	Found Brass Cap with 3/4" Iron Pipe along side, per CS RM3-48	Found B.T.: 26" Cedar, healed face & Tag, bears N58°E, 34.5' to SC per CS 53-66 & REM #40 Original 61" Cedar, healed face & Tag, bears S10°W, 11.9' to SC	19	Set 3" Aluminum Rock Cap on Boulder	Mkd. B.T.: 17" Douglas Fir F.S. "BT", Tags & Washer, bears S65°30'W, 6.7' to SC 16" Douglas Fir F.S. "BT", Tags & Washer, bears S19°E, 21.7'
10	Set 3" Aluminum Cap on 2 1/2" Aluminum Pipe	Mkd. B.T.: 14" Douglas Fir, F.S. "E1/16 S35 BT", Tags & Washer, bears S20°30'E, 21.89' to SC 14" Douglas Fir, F.S. "E1/16 S26 BT", Tags & Washer, bears N52°45'W, 13.39' to SC			

## SECTION 35 TOWNSHIP 20 SOUTH RANGE 11 WEST W. M.

**ABBREVIATIONS:**  
 B.S. = BARK SCRIBE  
 F&B = FRONT AND BACK  
 F.S. = FACE SCRIBE  
 B.T. = BEARING TREE  
 B.O. = BEARING OBJECT  
 R.M. = REFERENCE MONUMENT  
 SC = SIDE, CENTER  
 B.H. = BREAST HIGH  
 MKD. = MARKED  
 REM. = REMONUMENTATION RECORDS  
 STD. U.S.F.S. DISK = 3" ALUMINUM CAP ON 2 1/2" X 30" ALUMINUM PIPE

**REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR**  
*Harvey Wilcox*  
**OREGON**  
 JULY 17, 1988  
**HARVEY WILCOX**  
 2244

*Stuntzner Engineering & Forestry*

ENGINEERING - LAND SURVEYING - FORESTRY  
 PLANNING - WATER RIGHTS  
 705 South 4th, Post Office Box 118, Coos Bay, Oregon 97420  
 503-287-2872  
 503-287-0668 FAX

**COUNTY SURVEYORS FILE DATA  
 DO NOT REMOVE FROM OFFICE**

DRAWN BY: A.A.	DATE: 12-15-90
CHECKED BY: H.W.	DRAWING NO.: 9092A35B
JOB NO.: 90-92	SHEET 4 OF 6

MAP FILE M111-472-D