

**COUNTY SURVEYORS FILE DATA  
DO NOT REMOVE FROM OFFICE**

FILED  
FEB 11 1991  
COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.  
J.P.

**ESLICK CADASTRAL CONTRACT #53-04T0-0-2030S**

CORNER NO.	MONUMENT	ACCESSORIES	CORNER NO.	MONUMENT	ACCESSORIES
1	U.S.D.A. FOREST SERVICE T20S R11W S26 S25 S35 S36 1990 RLS2244	Mkd. B.T.: 38" Douglas Fir, F.S. "T20S R11W S25 BT", Tags & Washer bears N25°15'E, 39.45' to SC 16" Douglas Fir, F.S. "T20S R11W S36 BT", Tags & Washer bears S76°30'E, 13.77' to SC 40" Douglas Fir, School Warm, F.S. "T20S R11W S26 BT", Tags & Washer, bears N20°30'W, 3.12' to SC Set R.M.: Std. U.S.F.S. Disk "RM T20S R11W S26 S83°11'E, 40.56' 1990 RLS2244", bears N83°11'W, 40.56'	11	U.S.D.A. FOREST SERVICE T20S R11W S36 N1/16 1990 RLS2244	Mkd. B.T.: 9" Alder B.S. "CN1/16 S36 BT", Tags & Washer, bears N39°W, 22.80' to SC Mkd. B.O.: Rock Face with P.K. Nail & Washer in center of "X" and Tag, bears S61°W, 77.37' Found B.O.: 5/8" Iron Rod with plastic cap mkd. "STUNTZNER ENGR." bears S00°30'E, 60.63' Mkd. B.T.: 27" Douglas Fir, F.S. "C1/4 S36 BT", Tags & Washer, bears N60°15'W, 26.13' to SC 7" Douglas Fir, F.S. "C1/4 S36 BT", Tags & Washer, bears S24°15'W, 5.85' to SC 46" Cedar, F.S. "C1/4 S36 BT", Tags & Washer, bears N87°30'E, 90.57' to SC Set R.M.: Std. U.S.F.S. Disk: "RM C1/4 S36 S89°52'W, 73.15' 1990 RLS2244", bears N89°52'E, 73.15' Found B.T.: 45" Maple, visible scribe & F&B Tags, bears N65°W, 14.7' to SC per M84-62 26" Douglas Fir, healed face, F&B Tags, bears S52°E, 18.3' to SC per M84-62
2	U.S.D.A. FOREST SERVICE T20S R11W N1/16 S35 S36 1990 RLS2244	Mkd. B.T.: 44" Douglas Fir, F.S. "N1/16 S36 BT", Tags & Washer, bears N73°15'E, 59.13' to SC 19" Maple, F.S. "N1/16 S36 BT", Tags & Washer, bears N86°E, 21.80' to SC 25" Douglas Fir, F.S. "N 1/16 S35 BT", Tags & Washer, bears N87°30'W, 32.15' to SC	12	U.S.D.A. FOREST SERVICE T20S R11W C1/4 S36 1990 RLS2244	Mkd. B.T.: 22" Douglas Fir, F.S. "E1/4 S35 BT", Tags & Washer, bears N20°30'W, 61.00' to SC 31" Douglas Fir, F.S. "W1/4 S36 BT", Tags & Washer, bears N3°E, 21.25' to SC 31" Douglas Fir, F.S. "W1/4 S36 BT", Tags & Washer, bears S45°E, 6.10' to SC Mkd. B.O.: 5' high Rock Face with a P.K. Nail and Washer in the center of an "X" and Tag, bears N58°W, 18.60'
3	U.S.D.A. FOREST SERVICE T20S R11W S35 S36 1990 RLS2244	Mkd. B.T.: 15" Douglas Fir, F.S. "S1/16 S35 BT", Tags & Washer, bears N30°W, 31.68' to SC Set R.M.: Std. U.S.F.S. Disk "RM S1/16 S35 S88°04'E, 53.26' 1990 RLS2244", bears N88°04'W, 53.26'	13	1/4 T20S R11W S36 S1 T21S R11W 1980	Mkd. B.T.: 22" Alder, B.S. "E1/16 S25 BT", Tags & Washer, bears N41°E, 37.52' to SC 29" Cedar, FS "E1/16 S36 BT", Tags & Washer, bears S36 1/2'E, 57.95' to SC
4	U.S.D.A. FOREST SERVICE T20S R11W S35 S36 S1/16 1990 RLS2244	Found B.T.: 10" Douglas Fir, with "X" at B.H., bears West, 12.2' to SC 12" Douglas Fir, with visible Scribe, bears N44°W, 12.9' to SC 17" Douglas Fir, with healed face, bears S49°E, 7.5' to SC 11" Douglas Fir, with healed face, bears S24°W, 3.4' to SC	14	U.S.D.A. FOREST SERVICE T20S R11W S25 S36 1990 RLS2244	Mkd. B.T.: 48" Maple, F.S. "WP BT", Tags & Washer, bears N54 3/4'W, 87.96' to SC Mkd. B.O.: Rock Face, with P.K. Nail and Washer in the center of "X", Tag, bears N07 1/2'E, 48.47'
5	U.S.D.A. FOREST SERVICE T20S R11W S35 S36 S2 S1 PLS1342 T21S R11W 1980	Mkd. B.T.: 20" Douglas Fir, F.S. "W1/16 S25 BT", Tags & Washer, bears N21°W, 21.67' to SC 61" Douglas Fir w/ Open Face bears N46°W, 12.77' to SC 34" Hemlock F.S. "W1/16 S25 BT" Tags & Washer, bears N81°30'W, 15.14' to SC	15	U.S.D.A. FOREST SERVICE WP S36 GOVT GOVT LOT 2 LOT 1 1990 RLS2244	Mkd. B.T.: Original 32" Maple, rotten face, Tags, bears N29°W, 25.3' to SC 17" Cedar, healed face, Tags, bears N20°W, 47.3' to SC per CS 55-142 76" Spruce, visible scribe, Tags, bears S72 3/4'E, 74.3' to SC per CS M102-12 Cascara, dead, Tags, bears S72°E, 27.6' 65" Douglas Fir, visible scribe, Tags, bears S18°W, 70.3' per CS M10-3 & REM 10 Set R.M.: Std. U.S.F.S. Disk: "RM T20S R10W S30 S88°20'W 43.40' 1990 RLS2244", bears N88°20'E, 43.40'
6	U.S.D.A. FOREST SERVICE T20S R11W S25 W1/16 S36 1990 RLS2244	Mkd. B.T.: 39" Maple, F.S. "NW1/16 S36 BT", Tags & Washer, bears N6°E, 10.25' to SC Set R.M.: Std. U.S.F.S. Disk: "RM NW1/16 S36 N89°10'W, 38.20' 1990 RLS2244", bears S89°10'E, 38.20'	16	U.S.D.A. FOREST SERVICE WP S36 GOVT LOT 2 GOVT LOT 3 1990 RLS2244	Found B.O.: Fence Post with Nail in Top & Tag, bears S33°E, 36.2' per CS M85-37
7	U.S.D.A. FOREST SERVICE T20S R11W NW1/16 S36 1990 RLS2244	Mkd. B.T.: 23" Douglas Fir, F.S. "CW1/16 S36 BT", Tags & Washer, bears N86°30'E, 67.90' to SC Mkd. B.O.: Rock Face with P.K. Nail in the center of an "X", Tag, bears N5°15'W, 12.54'	17	T20S R 1 1 W 25 30 36 31 1970 LS850	Mkd. B.T.: 31" Douglas Fir, F.S. "S1/16 S36 BT", Tags & Washer, bears N83 3/4'W, 44.55' to SC 20" Douglas Fir, F.S. "S1/16 S31 BT", Tags & Washer, bears S03 1/2'E, 27.31' to SC
8	U.S.D.A. FOREST SERVICE T20S R11W W1/16 S36 1990 RLS2244	Mkd. B.T.: 11" Douglas Fir, F.S. "SW1/16 S36 BT", Tags & Washer, bears N55°45'W, 22.67' to SC 12" Douglas Fir, F.S. "SW1/16 S36 BT", Tags & Washer, bears N5°15'W, 24.68' to SC	18	1/4 36 31	Found B.T.: 30" Maple, S.E. trunk of tree with healed face, tags, bears N14°W, 15.2' to SC per REM #21 21" Douglas Fir, healed face, Tags, bears N80°E, 83.6' to SC per REM #48 37" Douglas Fir, healed face, Tags, bears S77 1/4'E, 42.9' to SC per REM #21 39" Maple, healed face, Tags, bears S27°W, 11.2' to SC per REM #21. NOTE: this tree trunk has blown down. I retagged another trunk of the same tree, it bears S25 1/2'W, 14.20' to SC Set R.M.: Std. U.S.F.S. Disk "RM T20S R10W S31 S88°09'W, 52.91 1990 RLS2244", bears N88°09'E, 52.91'
9	U.S.D.A. FOREST SERVICE T20S R11W SW1/16 S36 1990 RLS2244	Found B.T.: 52" Cedar, healed face, bears S87°W, 15.8' to SC 12" Hemlock, healed face, bears N70°W, 21.5' to SC 33" Cedar, healed face, bears S61°E (S61°W per CS 53-66), 32.7' to SC	19	U.S.D.A. FOREST SERVICE T20S R11W, R10W S36 S31 1990 RLS2244	Mkd. B.T.: 30" Maple, S.E. trunk of tree with healed face, tags, bears N14°W, 15.2' to SC per REM #21 21" Douglas Fir, healed face, Tags, bears N80°E, 83.6' to SC per REM #48 37" Douglas Fir, healed face, Tags, bears S77 1/4'E, 42.9' to SC per REM #21 39" Maple, healed face, Tags, bears S27°W, 11.2' to SC per REM #21. NOTE: this tree trunk has blown down. I retagged another trunk of the same tree, it bears S25 1/2'W, 14.20' to SC Set R.M.: Std. U.S.F.S. Disk "RM T20S R10W S31 S88°09'W, 52.91 1990 RLS2244", bears N88°09'E, 52.91'
10	T20S R11W 1/4 S25 S36 1966	Found B.T.: 52" Cedar, healed face, bears S87°W, 15.8' to SC 12" Hemlock, healed face, bears N70°W, 21.5' to SC 33" Cedar, healed face, bears S61°E (S61°W per CS 53-66), 32.7' to SC	20	T20S R 1 1 W S36 S31 S1 S6 T21S 1968	Found B.T.: 52" Cedar, healed face, bears S87°W, 15.8' to SC 12" Hemlock, healed face, bears N70°W, 21.5' to SC 33" Cedar, healed face, bears S61°E (S61°W per CS 53-66), 32.7' to SC

**SECTION 36  
TOWNSHIP 20 SOUTH  
RANGE 11 WEST  
W. M.**

- ABBREVIATIONS:**
- B.S. = BARK SCRIBE
  - F&B = FRONT AND BACK
  - F.S. = FACE SCRIBE
  - B.T. = BEARING TREE
  - B.O. = BEARING OBJECT
  - R.M. = REFERENCE MONUMENT
  - SC = SIDE, CENTER
  - B.H. = BREAST HIGH
  - MKD. = MARKED
  - GLV. = GALVANIZED
  - REM. = REMONUMENTATION RECORDS
  - STD. U.S.F.S. DISK = 3" ALUMINUM CAP ON 2 1/2" X 30" ALUMINUM PIPE

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Harvey Wilcox*

**OREGON  
JULY 17, 1989  
HARVEY WILCOX  
2244**

**Stuntzner Engineering & Forestry**

ENGINEERING - LAND SURVEYING - FORESTRY  
PLANNING - WATER RIGHTS

705 South 4th, Post Office Box 118, Coos Bay, Oregon 97420  
503-267-2872  
503-267-0668 FAX

DRAWN BY: A.A.	DATE: 12-15-90
CHECKED BY: H.W.	DRAWING NO.: 9092A36B
JOB NO.: 90-92	SHEET 6 of 6