

M.B. Germond

(Ren. #29)

N.E. Cor. Samuel Turner (F.B. 22 Page 5)

W. Oak 10" S. 50 1/2° E. 17 lks.

8" N. 1° E. 15.

S.W. Cor. D.L.C. - 51 (F.B. 43-P. 14)

F.C. Frear

Sept. 1917

JUN 3, 1935
F.C. Frear Surveyor
with { P.D. Wolford
J.H. Wolford
N.E. Richardson

JULY 27, 1936
A. Boyer, Sur.
W. Billick
F. A. Thomas

(Ren. #30)
(Ren. #33)

Set 1/2" X 30" G.I. Pipe

Fir 24" S. 27° E. 3 lks.

Oak 18" S. 69° W. 29 1/2

Cor to sec 20-21-28+29. Found one Old B.T. A White Oak 30" S 43 1/2° E 424.4 ft. Marks Plain. All other trees gone. Set a Cedar Stake in sawyer's Garden from which
36" Red Fir N 42° W 150° ft.
12" White Fir S 48 1/2° E 351° ft.

N.W. Cor D.L.C. 50. Reset from 8" Ash B.T. (Myrtle B.T. Cut out) by setting 6" x 12" x 20" Conc. Block from wh. a 12" Myrtle stump, abt 4' high, brs S 10 1/2° E 32.3'

H.T. Lewis

H.T. Lewis

22-9

Nov 19, 1936
A Boyer
Bert Lane
Will Garrison
(#1)

S.W. Cor D.L.C. 39, Set from orig hemlock B.T. to the NE
Set 3" x 3" x 36" Fir Post for cor. fr which a 15" Maple
brs S 71 1/2° W. 19.2' Mkd D.L.C. 39 B.T.

Nov 20, 1936
A Boyer D.C.S.
Bert Lane
Will Garrison
Fred Schindler
(#2)

Sec Cor to 5 1/4 8. Set from alder orig B.T. which is now dead
abt to fall - 1 1/2" x 36" Pipe for cor. from which a 20" Fir
brs S 52 1/2° E. 48.5' mkd. C.S. S.B. B.T. found 9" cut out Orig
B.T. Fir S 30° W 19.8'

Nov 21, 1936
A Boyer
Bert Lane
Will Garrison
Fred Schindler
(Rev. #3)

Cor. at Intersec. N. Line D.L.C. 38 9" line bet Sec 7 1/4 8.
Cross on rock fr. wh. 18" Fir Brs. N 58° W 17.1' Mkd

A Boyer
Will Garrison
Bert Lane
Fred Schindler
R.J. Andrews
(Rev. #4)

D.C.L. S 7 B.T.
NE Cor lot 12 Sec 8
Cor at Intersec Sec. Line bet 5 1/4 8 9" W. Line D.L.C. 39
3" x 3" x 30" Post, fr. wh. 40" Burly Maple Brs. N 43° E. 23.5'
Mkd L 12 B.T.
and a 20" Alder Brs. S 40° E 32.5' Mkd L 12 B.T.

H.T. Lewis
Engr # 722.
Oct. 18, 1929.
(Rev. #5)

REC. by H.L. Fpp
At the Corner of Secs. 35 & 36. T. 21 S. R. 9 W. W.M. & Secs. 1 & 2.
T. 22 S. R. 9 W, I found all witness trees in place, but
the hem locks, which are the trees for secs 35 + 36
have been killed by fire. I therefore set a hemlock post 4'
long, 4" diam., 18" in ground, from which;
A Hemlock 9" dia. bears N 47 1/2° W. 34 ft. Marked T. 21 S. R. 9 W. Sec 36. B.T.
A Fir, 36" dia., bears N 60° E 65 ft. Marked T. 21 S. R. 9 W. Sec 36 B.T. (E 19 W) 722.

H.T. Lewis
Engr. # 722
Sept 28 1939
(Rev. #6)

CORNER SECS. 15-16-21 & 22
At the corner of Sections 15-16-21 & 22, T. 22 S. R. 9 W. W.M.
I found the S.W. witness tree in good shape & evidence of
the NW & NE Trees, but no evidence of the corner post. I
therefore set a fir post 4' long, 4" dia., 18" in ground,
from which;
A. Fir 10" dia., bears S 89° E 11 ft. Marked T. 22 S. R. 9 W. Sect. 22 B.T. 722
A Fir 16" " " " N 45° E 9 ft. " " " " Sect. 15 " "
A. Fir 13" " " " N 40° W 54 ft. " " " " Sect. 16 " "

H.T. Lewis
Engr # 722
Sept. 29 1939
(Rev. #7)

Secs 16-17-20 & 21. AT the cor. of Secs, 16-17-20 & 21 T. 22 S. R. 9 W. W.M., I found the
S.W. witness tree in place, also faint marks on the rotten bark of the 60"
fir, described in the Government notes, but no evidence of Cor. Post.
I therefore set a fir Post 4' long & 4" in diam., 14" in ground from which
A. Maple, 14" dia. bears N. 31° E. 33 ft Marked T. 22 S. R. 9 W. sect. 16, B.T. 722
A Fir, 30" " " " N. 14° W. 30 ft. " " " " 17 " "
A Hemlock, 8" " " " S. 50° E. 7 ft. " " " " 21 " "