

**RESTORED CORNER FOR
STATE OF OREGON – DEPARTMENT OF FORESTRY**

Southeast corner for Section 36, Township 22 South, Range 11 West, W.M., Coos and Douglas Counties, Oregon.

ORIGINAL by William R. Whipple, 1894, Contract No. 612

No evidence of original corner found.

REESTABLISHMENT by Arnold G. Gibson, 1972

Oregon State Board of Forestry 1 ½" x 36" galvanized iron pipe with 3" bronze cap (found pulled out of the ground and lying downhill)

- 36" Fir N22 1/2°W 59.60 ft.; now 47" in place, face closed, yellow metal location poster.
- 21" Fir N63°W 79.70 ft.; now 21" x 2 ft. high rotted stump in place, partial scribes visible.
- 4" x 4" x 72" White Painted Cedar Post S25°E 2.0 ft.; missing.

RESTORED

Reset 1971 Oregon State Board of Forestry iron pipe with bronze cap 36" in ground from Gibson's 1971 BT's from which a:

- 44" Fir S82°E 109.00 ft. to aluminum nail in BT face scribed (T22SR10WS31BT) bearing tree tag.
- Carsonite witness post S20°E 5.70 ft. to base.
- Carsonite witness post N62°W 9.90 ft. to base.
- 4" x 4" x 72" White Painted Cedar Post N83°E 2.80 ft. to base.

Magnetic variation set at 19° East.

Dated July 14, 2011

Rewitnessed by Tim VanVleet under my direction.
Tim VanVleet

Restored By:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James M. McIntosh

OREGON
JULY 13, 1984
JAMES M. MCINTOSH
2103

James M. McIntosh
63612 Fifth Road
Coos Bay, Oregon

Expiration date of certificate 12-31-12

FILED

Date: 7/25/2011 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/72-31

**DOUGLAS COUNTY
SURVEYOR**

Present and witnessed by Ralph C. Hall

C.S. File No 65/72-31