

COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE

FILED
 Date: 4-29-2002 By: DC
 This survey consists of:
 Map: St Hwy 42-007A-H
 Narrative: _____
 Corner Rpt: _____
DOUGLAS COUNTY
SURVEYOR

POINT ID	LDP NORTHING	LDP EASTING	DESCRIPTION
1036	165751.033	372551.069	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. R/W 1489+00 45.0".
1038	165784.873	372646.452	FOUND 1 1/4" YELLOW PLASTIC CAP FLUSH WITH ASPHALT CONC. IN GOOD CONDITION. (REF. SURVEY #M112-16)
1040	165807.105	372709.075	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. 1494+50 45.0" FLUSH WITH ASPHALT CONC. IN GOOD CONDITION.
1041	165808.747	372713.683	FOUND 5/8" IRON REBAR 50 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY M48-19)
1042	165812.854	372725.252	FOUND 2" ALUM. CAP STAMPED "AA SURV. SERV." FLUSH WITH ASPHALT CONC. IN GOOD CONDITION. (REF. SURVEY #M89-61)
1043	165790.126	372749.305	FOUND 2" ALUM. CAP STAMPED "AA SURV. SERV." FLUSH WITH ASPHALT CONC. IN GOOD CONDITION. (REF. SURVEY #M89-61)
1044	165768.217	372742.927	FOUND 2" ALUM. CAP STAMPED "AA SURV. SERV." 50 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY #M89-61)
1046	165714.021	372727.214	FOUND 1 1/4" PLASTIC CAP STAMPED "AA SURVEYING INC." FLUSH WITH ASPHALT CONC. IN GOOD CONDITION. (REF. SURVEY #M124-52)
1047	165673.636	372715.482	FOUND 1 1/4" PLASTIC CAP STAMPED "AA SURVEYING INC." 50 mm BELOW SURFACE IN FAIR CONDITION. (REF. SURVEY #M124-52)
1049	165640.545	372705.655	FOUND 5/8" IRON ROD FLUSH WITH SURFACE IN FAIR CONDITION. LEANING TO N.E. (REF. SURVEY #M46-6)
1050	165560.693	372682.363	FOUND 1 1/2" ALUM. CAP STAMPED "STATE HWY. DIV. 45.0" 30 mm BELOW SURFACE IN GOOD CONDITION.
1051	165649.514	372736.853	FOUND 1 1/4" PLASTIC CAP STAMPED "BENTZ SUR. INC." FLUSH WITH ASPHALT CONC. IN GOOD CONDITION. (REF. SURVEY #M104-39)
1052	165670.344	372742.923	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "BENTZ SUR. INC." FLUSH WITH ASPHALT CONC. IN GOOD CONDITION. (REF. SURVEY #M104-39)
1054	165697.752	372750.933	FOUND 1 1/4" PLASTIC CAP FLUSH WITH ASPHALT CONC. IN GOOD CONDITION. (REF. SURVEY #M104-39)
1055	165715.782	372756.156	FOUND 5/8" IRON ROD FLUSH WITH ASPHALT CONC. IN GOOD CONDITION.
1057	165763.386	372769.979	FOUND 5/8" IRON ROD 30 mm BELOW PAVEMENT IN GOOD CONDITION. (REF. SURVEY #M93-22)
1058	165772.453	372772.740	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. 1176+50 45.0" 20 mm BELOW SURFACE IN GOOD CONDITION.
1061	165781.662	372775.388	FOUND 5/8" IRON ROD 40 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY #M93-22)
1062	165798.872	372780.454	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DEPT." 20 mm BELOW ASPHALT CONC. IN GOOD CONDITION.
1064	165847.728	372794.726	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DEPT." 30 mm BELOW SURFACE IN GOOD CONDITION.
1077	166159.485	372899.649	FOUND 5/8" IRON ROD FLUSH IN ASPHALT CONC. IN GOOD CONDITION WITH PLASTIC CAP DESTROYED. (REF. SURVEY 1993-0104A)
1078	166187.157	372919.501	FOUND 5/8" IRON ROD WITH A 1 1/4" YELLOW PLASTIC CAP STAMPED "AA SURVEYING INC." 40 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY 1994-0058A)
1079	166197.531	372926.974	FOUND 5/8" IRON REBAR 50 mm ABOVE SURFACE IN GOOD CONDITION.
1080	166199.552	372928.481	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. 1191+70.29 50.0". SET FLUSH IN ASPHALT CONC. IN GOOD CONDITION.
1081	166208.012	372934.878	FOUND 5/8" IRON REBAR 50 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY #M73-45)
1085	165852.403	372761.177	FOUND TACK IN LEAD IN CONC. CURB FLUSH WITH SURFACE IN GOOD CONDITION. (EQUATION STATION 1497+13.66 = 1178+91.51, 64.96 FT. LT.)
1086	165843.021	372793.351	FOUND 5/8" IRON ROD 70 mm BELOW SURFACE IN GOOD CONDITION.
1087	165851.429	372793.064	FOUND TACK IN LEAD IN CONC. CURB IN GOOD CONDITION.
1090	166139.901	372855.274	FOUND 5/8" IRON REBAR 10 mm BELOW SURFACE IN GOOD CONDITION. STA. 1188+77.23 P.S.C., 45.00 FT. LT.
1093	166141.958	372887.048	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV. 1189+30.29 PCS 45.0 RT." 100 mm BELOW SURFACE IN GOOD CONDITION.
1100	166238.959	372922.118	FOUND 1 1/2" ALUM. CAP STAMPED "OREG. STATE HWY. DIV." FLUSH WITH SURFACE IN GOOD CONDITION.
1102	165749.350	372477.952	FOUND 1" IRON ROD 60 mm BELOW SURFACE IN GOOD CONDITION.
1103	165725.928	372410.126	FOUND 5/8" IRON REBAR 40 mm ABOVE SURFACE IN GOOD CONDITION.
1104	165725.349	372478.708	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "BTS ENG SURV" FLUSH WITH SURFACE IN GOOD CONDITION. (REF. SURVEY #2000-0024)
1105	165730.231	372492.399	FOUND 1 1/4" YELLOW PLASTIC CAP STAMPED "BTS ENG. SURV." 40 mm ABOVE SURFACE IN GOOD CONDITION. (REF. SURVEY #2000-0024)
1106	165772.095	372610.415	FOUND 5/8" IRON ROD FLUSH WITH ASPHALT CONC. IN GOOD CONDITION.
1187	165869.782	372689.158	FOUND 1/2" IRON ROD 110 mm BELOW SURFACE IN GOOD CONDITION. (REF. SURVEY #M74-37)
1188	165868.642	372719.487	FOUND 1/2" IRON ROD 300 mm BELOW SURFACE IN GOOD CONDITION. (REF. JUNCTION SUBD., VOL. 6, PG. 18)
1189	165868.345	372727.087	FOUND 1 1/2" O.D. IRON PIPE 470 mm BELOW SURFACE IN GOOD CONDITION. (REF. JUNCTION SUB., VOL. 6, PG. 18)
1190	165881.606	372741.292	FOUND 1 1/2" O.D. IRON PIPE 270 mm BELOW SURFACE IN GOOD CONDITION. (REF. JUNCTION SUB., VOL. 6, PG. 18)
G675	165829.572	372760.872	FOUND 2 3/4" BRASS DISK STAMPED "STATE HIGHWAY DEPARTMENT FEET B.M. NO. G675" SET FLUSH WITH CONC. IN GOOD CONDITION.

REFERENCE SURVEYS:

- 1990-0020
- 1992-0018
- 1992-0019
- 1993-0104A
- 1994-0058A
- 1997-0112
- 1998-0106
- 2000-0024
- JUNCTION SUBD., VOL. 6, PG. 18
- M46-6
- M48-19
- M62-40
- M66-17
- M71-26
- M73-45
- M74-37
- M76-63
- M81-32
- M89-61
- M93-22
- M100-45
- M101-34
- M104-39
- M112-16
- M114-53
- M117-40
- M120-19
- M124-52
- M128-28
- M129-14
- M129-21
- ODOT DRG. NOS. 9B-7-5, 6B-28-22, & 1A-22-13
- ST. HWY. IS-006, A-L
- WINSTON HOMES, VOL.8, PG. 19

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Christine V. Blawie

OREGON
 JULY 19, 1994
 CHRISTINE V. BLAWIE
 2669

EXPIRES: DEC. 31, 2003



1 METER = 3937 U.S. FEET / 1200
 TO CONVERT A METRIC DISTANCE DIVIDE BY 0.30480061

OREGON DEPARTMENT OF TRANSPORTATION
 HORIZONTAL CONTROL, RECOVERY,
 AND RETRACEMENT MAP
 WINSTON - INTERSTATE 5
 COOS BAY - ROSEBURG HWY.
 DOUGLAS COUNTY
 3500 STEWART PARKWAY, SUITE 140
 ROSEBURG, OREGON 97470

APRIL 23, 2002
 PROJECT KEY *09841

SHEET 3 OF 8

ST. HWY. 42-007C